Each

Dart Aerospace Ltd. wuesday, 16/09/2008 7:58:46 AM User: Melanie Fauteux **Process Sheet** Customer : CC-DAR01 Dart Aerospace Ltd. **Drawing Name** : REWORK 11 Job Number : 42016 **Estimate Number** : 10804 P.O. Number : REWORK11 Part Number : NCR08-087 This Issue : 16/09/2008 S.O. No. : **Drawing Number** : NC Prsht Rev. Project Number : // : CROSSTUBES First Issue Type **Drawing Revision** : 00015 **Previous Run** Material **Due Date** : 23/09/2008 Qty: 1 Um: Written By Checked & Approved By Comment **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: CROSSTUBES **CROSSTUBES RESOURCE 1** Comment: CROSSTUBES RESOURCE 1 Re-work the following crosstubes to re-position the clamps at the correct location, as per the dwg, and NCR08-087: -D206-667-203 B40116 *1 -D206-667-201 B41539 X \ -D206-667-201 B41540 x t -D407-667-105 B41405 x 1 08 09 16 -D407-667-105 B41406 🔀 1 2.0 QC5 INSPECT WORK TO CURRENT STEP 18.09.16 Comment: INSPECT WORK TO CURRENT STEP -Ensure the correct x-tubes are in the correct original box. 3.0 PACKAGING 1 PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

-Re-package the crosstubes with the original batch #'s.

-Ensure the correct x-tubes are in the correct original box.

-Return to stock.

QC5

4.0

INSPECT WORK TO CURRENT STEP

Comment: INSPECT WORK TO CURRENT STEP

-Ensure the correct x-tubes are in the correct original box.



Date:

Tuesday, 16/09/2008 7:58:46 AM

User:

Melanie Fauteux

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: REWORK 11

Job Number: 42016

Part Number: REWORK11

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Place a copy of this w/o to each of the original workorders affected.

mf 08-09-22

Job Completion

